



Performance Solution Scenario

PAA Access Consultants

www.paaaccess.au

projects@paaaccess.au

1300 860 009

Stair Width

Identified Design Issue

The stairway will have a reduced width of less than 1000mm between handrails.

Departure from Deemed-to-Satisfy Provisions

Due to spatial constraints within the building, a minimum clearance of 1000mm between handrails cannot be achieved in the stairway flight.

The Performance Solution

From an egress perspective, in a building with a low number of occupants on the upper level, single-file evacuation via the staircase can be completed before emergency services arrive, eliminating the need for a full 1000mm clearance.

This example is a hypothetical scenario and must not be used for any specific project.

Assessments must be tailored for each project.

Contact us to learn more.

We are experts at preparing Performance Solution Reports.

