



Performance Solution Scenario

PAA Access Consultants

www.paaaccess.au

projects@paaaccess.au

1300 860 009

Automated Swing Entry Door

Identified Design Issue

A landing between the swing door and ramp will not be provided.

Departure from Deemed-to-Satisfy Provisions

Due to the spatial constraints within the building, a 1450mm deep landing will not be provided between the swing door and the commencement of the ramp.

The Performance Solution


The swing door will be automated with a power-operated device meeting AS 5007 to offset the reduced landing. This solution further enhances accessibility by removing the need for manual door operation.

This example is a hypothetical scenario and must not be used for any specific project.

Assessments must be tailored for each project.

Contact us to learn more.

We are experts at preparing Performance Solution Reports.



Disclaimer: This publication provides general information only and does not constitute legal, certification or project-specific advice. Requirements may vary between projects and change over time. Always verify the current NCC, legislation and applicable Australian Standards, and obtain project-specific advice where required.

Images: PICCI-supplied imagery is licensed to the publisher and may not be reproduced or modified without permission. Third-party content remains subject to its applicable licence. Images are illustrative unless stated otherwise