



Mini DC Compressor Wiring Diagram




The Driver Board Wiring Diagram

A Positive wire Power “ + ”

B Negative wire Power “ - ”

- ① Switch (on-off), Enable terminal, reservation for EN.
- ② PWN speed control terminal (0~5V,1K~10KHz).
- ③ Fault alarm compressor failure alarm, high level-normal, low level-failure.
- ④ Connecting lines (Connecting to the compressor).
- ⑤ TTL communication port
- ⑥ 0~5V to adjust the speed.
- ⑦ Terminals for potentiometers with 50k ohm to adjust speed.
- ⑧ Control program edit input socket
- ⑨ Green LED
- ⑩ Red LED





The Driver Board Wiring Diagram

