



METHOD CNC ENGRAVING GUIDE




45 DEGREE 'V' BIT

THIS AREA HAS BEEN FACEMILLED PRIOR TO ENGRAVING

THIS AREA HAS NOT BEEN FACEMILLED - NOTE IT IS DEEPER ON ONE SIDE

