



Performance Solution Scenario

PAA Access Consultants

www.paaaccess.au

projects@paaaccess.au

1300 860 009

Accessible Parking Space Layout

Identified Design Issue

The accessible car parking design differs from the requirements of AS/NZS 2690.6.

Departure from Deemed-to-Satisfy Provisions

Due to the existing column on the car parking level, the accessible parking space will not meet the AS/NZS 2890.6 requirements, with a space measuring 4800mm wide x 5400mm long (overall, including the 2400mm wide x 5400mm long shared area).

The Performance Solution

The existing column in the corner of the shared area will be accepted, as it is outside the manoeuvring area, and the design will still comply with all other aspects of AS/NZS 2690.6, including the symbol, sign, linemarking and bollard.

This example is a hypothetical scenario and must not be used for any specific project.

Assessments must be tailored for each project.

Contact us to learn more.

We are experts at preparing Performance Solution Reports.



Disclaimer: This publication provides general information only and does not constitute legal, certification or project-specific advice. Requirements may vary between projects and change over time. Always verify the current NCC, legislation and applicable Australian Standards, and obtain project-specific advice where required.

Images: PICCI-supplied imagery is licensed to the publisher and may not be reproduced or modified without permission. Third-party content remains subject to its applicable licence. Images are illustrative unless stated otherwise

Performance Solution Scenario – Copyright © PAA Access Consultants 2026

Ref: PSFS10 Accessible Parking Space Layout 20260908