



Performance Solution Scenario

PAA Access Consultants

www.paaaccess.au

projects@paaaccess.au

1300 860 009

Ambulant Toilet Width

Identified Design Issue

Existing conditions result in a clearance of 890mm, instead of 900mm to 920mm.

Departure from Deemed-to-Satisfy Provisions

The existing walls are structural and would require significant work to increase the toilet to a 900mm width.

The Performance Solution

Using a 30mm or 32mm grabrail will help to maximise the clearance in the toilet area and maintain the relationship between the pan location and each grabrail.

This example is a hypothetical scenario and must not be used for any specific project.

Assessments must be tailored for each project.

Contact us to learn more.
We are experts at preparing
Performance Solution
Reports.

