Performance Solution Scenario

PAA Access Consultants

www.paaaccess.au projects@paaaccess.au 1300 860 009

Accessible Sauna Door

Identified Design Issue

The latch-side clearance inside the small sauna room will be slightly less than required (510mm).

Departure from Deemed-to-Satisfy Provisions

Due to the limited space inside the small sauna room, the approach could accept a reduced latch-side clearance. This could consider the room's use and the expected number of people in the sauna.

The Performance Solution

Removing the door controls from the door leaf will allow the door to be pushed open from inside the room. As a contingency, the room could be equipped with safety controls to alert operators to issues within the room.

This example is a hypothetical scenario and must not be used for any specific project.

Assessments must be tailored for each project.

Contact us to learn more.

We are experts at preparing Performance Solution Reports.



Disclaimer: This publication provides general information only and does not constitute legal, certification or project-specific advice. Requirements may vary between projects and change over time. Always verify the current NCC, legislation and applicable Australian Standards, and obtain project-specific advice where required.

Images: PICCI-supplied imagery is licensed to the publisher and may not be reproduced or modified without permission. Third-party content remains subject to its applicable licence. Images are illustrative unless stated otherwise